

Oil Field Environmental Incident Summary

Incident: 20150929131057 **Date/Time of Notice:** 09/29/2015 13:10

Responsible Party: WHITING OIL AND GAS CORPORATION

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: P JACKMAN 156-100-2-18-19-15H

Field Name: EAST FORK

Well File #: 29222

Date Incident: 9/29/2015 **Time Incident:** 06:34

Facility ID Number:

County: WILLIAMS

Twp: 156

Rng: 100

Sec: 18

Qtr: NE NW

Location Description: Misted oil and fire were on south edge of pad

Submitted By: Corissa Zimmer

Received By:

Contact Person: Corissa Zimmer
1700 BROADWAY STE 2300
DENVER, CO 80290

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident: Fire

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.2	Barrels	0.1	Barrels	0.1	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 11/27/2015 **Clean Up Concluded:** 10/6/2015

Risk Evaluation:

None noted, fire has been extinguished.

Areal Extent:

The fire was on the south side of the pad and impacted the edge of the pad and the adjacent field.

Potential Environmental Impacts:

None noted.

Action Taken or Planned:

The flare stopped misting oil and the fire was extinguished. Whiting will further investigate the root cause of the scrubber causing the spill to develop best management practices to avoid a reoccurrence.

Wastes Disposal Location: Wastes will be disposed of at an approved disposal.

Agencies Involved:

Updates

Date: 9/29/2015 **Status:** Reviewed - Follow-up Required

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Fire with released fluids impacted areas off location. Followup is required.

Date: 10/7/2015 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 10/7/2015.

No sign of spill at the time of inspection.

No follow-up is necessary.